

BONDI PAVILION RESTORATION AND CONSERVATION PROJECT



Bondi Pavilion – Upcoming Works

Upcoming Works

- North and South Pavilion tiled roofs complete
- South Pavilion tiled roof complete
- Western Landscape Stage 3B/3C Commenced
- Main Pavilion Atrium LVLs installed
- Main Pavilion Atrium Glazing frame and glazing
- Main Pavilion Lift installation complete
- Northern Pavilion Colonnade Waterproofing
- Southern Pavilion Radio Room Acoustic Slabs Ground and First Floor
- Gatehouse fit out complete
- Gatehouse archway remedial works commenced

Progress Photos

Installation of Precast Stairs – North Elevation



Progress Photos

Installation of Precast Stairs – South Elevation



Progress Photos

North Colonnade Roof slab pour



Progress Photos

Southern Colonnade slab formwork



Progress Photos

Theatre Strengthening Plates





Bondi Pavilion – Completed Works

- North and South Colonnades Roof slabs poured
- Precast Balustrades and stairs to North and South elevations of Main Pavilion
- Roof tiling to North and South Pavilions
- Western Landscape Stage 3a
- Lift installation
- Main Pavilion Theatre truss and roof
- Main Pavilion services installation
- Main Switchboard Isolated